

Statement of Evidence:

M111

North Quarter Corner of Section 11, Township 36 North, Range 31 West, Sauk Rapids Township, 4th Principal Meridian, Benton County, Minnesota.

1850 Original U.S. General Land Office survey established this corner and set a wood post at this location with bearing trees recorded:

8" Tamarack	S 75 W	20 links
8" Tamarack	N 69 E	16 links

1999 Information from Bill Lunser, LS 9394, shows he set the corner in March, 1999 at the split between section corners and on an extension of fence line from the NW corner through a fence corner 170 feet, more or less, west of the ¼ corner. Ties:

4" Poplar	NE	26.55
12" Poplar	NE	43.9
10" Poplar	SE	31.47
8" Birch	SE	18.18

2002 No resurvey information was found on this corner in the Benton County records.

2003 Linda Brown, LS 23682, found a 1 ½ " iron pipe with a ½ " iron pipe inside with cap No. 9394. Pipe was found to be 13.67 feet north of straight line between section corners at the approximate midpoint.

County Coordinates to iron pipe (#9394) obtained from SEPI traverse information:

NAD 83 (1996 Adjustment)
N-126551.337
E-470560.883