

Statement of Evidence:

G063

East Quarter Corner of Section 6, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.

10" Blk Oak S 74 1/2 W 277 links

1923 County Engineer's Notebook No. 40 contains a survey for CAR No. 1 running south to north. Notes corner marked by an iron with ties:

3" Oak	SE	39.9'
Stake	W	33'

Stationing gives distances of 2712.0 feet to the SE corner and 2826.4 feet to the NE corner with a deflection angle of 0-10' left (running south to north).

County Surveyor's Record Book 1, page 397, notes the same ties.

1938 County Engineer's Notebook No. 116 contains a survey for SAR No. 1 that notes the following ties to a spike in road:

2" Oak	NE	33.8
2" Oak	SE	42.9

Stationing gives distances of 2712.2 feet to the SE corner and 2828.1 feet to the NE corner with a deflection angle of 0-10' left (running south to north).

1977 County Engineer's ties:

4"Boxelder	NE	76.95
4" Boxelder	E	77.15
PP	SE	74.25
Bolt in Steel Post	W	127.44

2007 Westwood Professional Services Inc. found a 1/2" open iron at the centerline of road north/south.

2008 The County Surveyor's Office searched and found a 1/2" open pipe 0.8 ft. east of centerline and down 0.4 ft. in the bituminous in CSAH No. 1. Measurements to the NE and SE Corners of Sec. 6 give 2834.37 ft. and 2705.24 ft, respectively, and the deflection angle measured going south to north measures 0°14'42" left, which reasonably agree with 1923 and 1938 measurements. The 1/2" monument also fits with the Bolt in Steel Post tie from 1977 (meas. 127.54 ft.). The pipe is accepted as marking the best evidence and ties were made.

County Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N- 161492.331

E- 484406.102