

Statement of Evidence:

G173

East Quarter Corner of Section 17, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

10" Aspen	S 30 E	220 links
8" Aspen	S 6 1/2 W	296 links

1882 Affidavit (Doc. No. 26944-Book 1 of Misc., page 95) in 1908 by Wm. Dunsmore states that he owned the SE $\frac{1}{4}$ of Section 17, T 37, R30 in 1882 and that he had the land surveyed by Mr. Cronk, County Surveyor, and that the line fence was built between Sections 16 and 17 according to said survey and the government marks found.

2002 No resurvey information was found on this corner in the Benton County records.

2008 Westwood Professional Services Inc. found a $\frac{1}{2}$ " open iron pipe which falls 4.5 feet east and 2.5 feet south of the lost position. The iron pipe falls in the east-west centerline of a gravel road and on a fence to the north. The iron pipe is accepted as marking the obliterated corner position, new reference ties were taken and coordinates were acquired.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-150797.309

E-489685.961