

Statement of Evidence:

G223

East Quarter Corner of Section 22, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

| | | |
|-----------|--------|----------|
| 8" Aspen | N 31 W | 10 links |
| 10" Aspen | East | 19 links |

Undated County Surveyor's Record Book 1, page 431, notes the following reference tie:

| | | |
|-------------|------|--------------|
| 10" Blk Oak | West | 16 1/2 links |
|-------------|------|--------------|

1977 Paul Wellen's, LS 10461, show corner used in survey subdividing Section 22.

2009 The Benton County Surveyor's Office found a 1/2" iron pipe down 0.5 feet on a fence to the west and south. The iron pipe falls 17.5 feet east and 4.8 feet north of the lost position. No evidence of the 10" Black Oak was found. The 1/2" iron pipe is accepted as the best available evidence of the corner position.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-145489.168

E-500220.071