

Statement of Evidence:

East Quarter Corner of Section 24, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1849 Corner established by Original US General Land Office survey and marked by a wood post with bearing trees noted as.

10" Elm	N 28 E	11 links
12" Elm	S 59 W	12 links

Line trees were noted as a 8" W Birch, South, 19.32 chains and a 6" Poplar, North, 20.45 chains.

2002 No record evidence of this corner has been found in the Benton County records.

2010 The Benton County Surveyor's Office found a ½" iron pipe capped RLS 23044 at the lost position falling on the extension of a fence west and 78 feet east of a fence north, measuring 2676.77 feet to the section corners north and south. The fence north looks to be a fence of convenience, not a line fence. With no other evidence to consider the found iron is accepted as marking the corner position. GPS coordinates were obtained.

Coordinates Obtained by GPS

NAD 83 (1996 Adjustment)

N-145483.764

E-510757.761