

Statement of Evidence:

G333

East Quarter Corner of Section 33, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

- 1852 Original US General Land Office survey set a wood post with bearing trees noted as.

16" Aspen	S 30 W	168 links
18" Bur Oak	N 25 1/3 E	138 links

- 2001 William Lunser, LS 9394, found a 1/2" pipe at the intersection of a fence line (east/west) and an occupation line (south). He filed a Certificate of Location (#283105). He notes a distance of 2621.09 feet to the NE corner Sec 33 and a distance of 2642.22 feet to the SE corner Sec 33.
- 2002 No record evidence of this corner has been found in the Benton County records.
- 2007 Westwood Professional Services, Inc. found a 1/2" open iron pipe in wood line east and west also noting a down fence running east and west from corner position.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N-134898.872
E-494646.541

- 2012 The Benton County Surveyor's Office reviewed the corner location. The corner falls 8.9 feet west and 10.9 feet north of the lost position. Since the corner falls on the east-west fence, near the occupation line south, it is accepted as the best available evidence of the corner position.