

Statement of Evidence:

G021

North Quarter Corner of Section 2, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1849 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as.

4" Tamarack	S 10 W	127 links
4" Tamarack	N 36 E	420 links

Line trees were noted as a 6" Tamarack, East, 19.84 chains and a 12" W Oak, West, 19.24 chains.

2002 No resurvey information was found on this corner in the Benton County records.

2008 Westwood Professional Services Inc. found a 1/2" iron pipe of unknown origin which appears to have been set at a lost position. New ties were measured and noted.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 164374.230
E- 503041.778

2010 The Benton County Surveyor's Office found a 1/2" iron pipe capped 19552.