

Statement of Evidence:

G131

North Quarter Corner of Section 13, Township 37 North, Range 30 West, 4th Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey established corner marked by a wood post with bearing trees noted as:

24" W Elm	N 52 E	25 links
10" Aspen	S 20 W	12 links

1899 Road Survey Report by John E. Whilt, County Surveyor, shows survey running west to east on section line with a distance of 79.72 chains for the north line of Sec. 13, with no mention of the 1/4 corner.

2008 Westwood Professional Services found a 1/2" iron pipe in the east-west centerline of a gravel road and on a long standing occupation line south. The iron falls 6 feet north and 6.5 feet east of the lost position. The iron pipe is accepted as marking the obliterated corner position.

Coordinates Obtained by GPS
NAD 83 (1996 Adjustment)
N- 153476.981
E- 508241.331