

Certified, Filed and or Recorded on  
Mar. 23, 2010 AT 11:49AM


Signed: MJ  
MARILYN J NOVAK G V I  
BENTON COUNTY MINNESOTA  
MARILYN J NOVAK  
COUNTY RECORDER

## CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH 1 QUARTER Corner of Section 28, Township 37, Range 30  
4TH Principal Meridian, State of Minnesota, County of Benton

At the corner location shown on the sketch:

On \_\_\_\_\_ found a \_\_\_\_\_  
 left monument as found     lowered monument     removed monument (explain)  
 On 8-1-06 placed an 1/2" I.P. # 19552  
 DATE



Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision and that I am a licensed Land Surveyor under the laws of the State of Minnesota.

Signature Jerome C. Wittstock Date 3-22-2010 License No. 19552  
 Title  Land Surveyor  Professional Engineer  County Surveyor  County Engineer

Benton County Surveyor's Office  
Jerome C. Wittstock, County Surveyor  
Minnesota License No. 19552

### **Statement of Evidence:**

G281

North Quarter Corner of Section 28, Township 37 North, Range 30 West, 4<sup>th</sup> Principal Meridian, Mayhew Lake Township, Benton County, Minnesota.

1852 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" Aspen S 24 E 466 links

2002 No record evidence of this corner has been found in the Benton County records.

2006 The Benton County Surveyor's Office found an east-west fence line and a field fence line (not line fence) south. The east-west fence, when projected west, falls 28 feet south of the section corner and truncates at the west sixteenth (not built to the section corner). Believing the east-west fence to not be built on the section line and the fence south to be a fence of convenience, a ½-inch iron pipe capped RLS 19552 was set at the lost position.

Coordinates Obtained by GPS  
NAD 83 (1996 Adjustment)  
N-142819.723  
E-492124.209