

Statement of Evidence:

1203

East Quarter Corner of Section 20, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" Blk Ash	N 10 W	27 links
12" Blk Ash	N 12 E	46 links

1938 County Engineers' Notebook No. 119 shows survey of CAR 27 running from north to south. Notes show corner being a set spike in center of road on east and west fence lines. Ties:

TP	W	48.9'
PP	SW	48.1'

Stationing gives distances of 2633.7 feet to the NE corner and 2662.7 feet to the SE corner with a delta angle of 0-41' left.

1951 MN/DOT alignment map for TH 23 shows corner assumed in center of north-south road and in line with fences east and west, being 1669.9 feet south of centerline.

1962 County Surveyor's Record Book 2, page 424, gives ties to an iron placed:

TP	W	49.6
PP	SW	55.1
TP	E	32.6

2001 William Lunser, LS 9394, found a nail in center of north-south town road and in line with fences east and west. Measured 2630.39 feet to the NE corner and 2662.74 feet to the SE corner. He accepted the nail as marking the obliterated corner and replaced it with a ½" iron pipe. Tie to PP SW 53.75'.

2011 The Benton County Surveyors' Office found a ½ inch iron pipe with an unreadable cap on the centerline of the North-South road and in line with fences east and west. Distances to the Northeast and Southeast corners measured 2630.33 feet to the Northeast and 2662.72 feet to the Southeast. The ½ inch iron pipe with an unreadable cap is accepted as the marking the obliterated corner position based on the 1938 corner referenced in the County Engineers' Notebook No. 119.

County Coordinates
NAD 83 (1996 Adjustment)
N- 145719.832
E- 552633.993