

Statement of Evidence:

East Quarter Corner of Section 19, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

22" W Oak	N 62 W	7 links
18" W Oak	N 58 1/2 E	65 links

1951 MN/DOT alignment map for TH 23 shows corner assumed in center of north-south road and fence line west. Corner is 1277.1 feet north of centerline of TH 23.

2001 William Lunser, LS 9394, found a 1/2 " iron pipe in center of north-south road and filed a Certificate of Location (No. 283118).

2002 Sam Deleo, LS 40341, found 3/4 " iron pipe at surface with a 1/2 " iron pipe below down 8" in the center of CSAH No. 6. He notes irons fit reasonably well with highway plans and the plat of ST. FRANCIS in the City of Ronneby. He replaced both pipes with a cast iron monument.

2003 Sam Deleo filed Certificate of Location (Doc. 298888).

County Coordinates
NAD 83 (1996 Adjustment)
N-
E-