

Statement of Evidence:

Northeast Corner of Section 32, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" Blk Ash	S 63 1/2 E	14 links
12" Blk Ash	S 24 W	24 links

1912 County Surveyor's Record Book 2, on pages 442 and 443, and Record Book A, Map No. 18, shows a survey of Section 29 by Samuel S. Chute. Corner is shown as marked by a stone.

1938 County Engineers' Notebook No. 119 shows survey of CAR 27 running from north to south. Notes show corner being a set spike in center of road at intersection with east and west road (SAR 4). Ties:

FP	NE	51.3'
FP	SE	53.3'

1940's County Engineer's Notebook No. 160 contains road survey for SAR No. 4 running west to east along the section line. Corner is shown as a 2" hub set in center of road with CAR 27 north and south. Ties:

NE Cor. House	SW	132.8
8" W. Oak	SE	137.2
10" W. Oak	SE	92.9

No Date ties: County Surveyor's Record Book 2, page 448:

FP	SW	43.4
TP	NW	39.5
10" Maple	SE	96.0

1993 Sidney Williamson, LS 10918, found a PK nail 10 feet south of the center of CSAH 4 and replaced it with a CIM. Certificate of Location filed (No. 227425).

NOTE: Corner should be excavated to check for stone. Need to check for old ties.

County Coordinates
NAD 83 (1996 Adjustment)
N-
E-