

Statement of Evidence:

The Northeast Corner of Section 24, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

30" W Ash	S 41 W	55 links
20" W Ash	S 72 E	30 links
22" W Ash	N 82 W	8 links
20" Sugar	N 56 E	92 links

Line trees were noted as a 10" Basswood North 20.49 chains and a 22" Pine South 17.88 chains.

No Date County Surveyor's Record Book 2, page 432, lists ties:

8" W. Ash	S 59 E	78 links
8" W. Elm	N 62 3/4 W	88 links

1996 John Oliver, LS 8194, Mille Lacs County Surveyor, set 3/4 " iron pipe by single proportion method between the NW corner Section 30 and the NW corner of Section 7, 37-27, but on the centerline of the north-south road and filed Certificate of Location (No. 244627). Corner falls in 4-way road intersection. Corner area was excavated and no evidence found of a corner marker. (See Certificate for details.)

2003 Survey & Engineering Professionals, Inc. (Linda Brown, LS 23682) found iron pipe and coordinates determined from their traverse information.

County Coordinates by Traverse (SEPI)

NAD 83 (1996 Adjustment)

N- 148649.145

E- 573725.621

2008 The County Surveyor's Office searched and found Oliver's 1996 3/4" iron pipe approximately 0.4' below the surface at the intersection of east-west gravel road (85th Street N.E.) and north-south gravel road (195th Avenue N.E.). Position distance to East 1/4 corner of Section 13 gives 2634.60 feet which agrees well with Oliver's 1996 distance. The Surveyor accepts the position as the best evidence and updated ties.

County Coordinates by GPS to 3/4" iron pipe

NAD 83 (1996 Adjustment)

N- 148648.955

E- 573725.799