

Statement of Evidence:

I132

Northeast Corner of Section 13, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1849 Original US General Land Office surveyor, Theodore Conkey, set a wood post at this location and bearing trees were recorded.

16" Elm	S 76 E	37 links
12" Pine	S 52 W	50 links
14" Elm	N 51 E	39 links
12" W Oak	N 35 E	46 links

Line trees were noted as a 30" Pine South 16.85 chains and a 6" Poplar North 23.16 chains.

1996 John Oliver, LS 8194, Mille Lacs County Surveyor, set corner lost and filed Certificate of Location (No. 244625). Corner falls in center of east-west road and 18 feet east of north-south road centerline. (See Cert. for details.) Corner monument set was a $\frac{3}{4}$ " iron pipe.

2002 No resurvey information was found on this corner in the Benton County records.

2003 Survey & Engineering Professionals, Inc. (Linda Brown, LS 23682) found iron pipe and coordinates determined from their traverse information.
County Coordinates by Traverse (SEPI)
NAD 83 (1996 Adjustment)
N- 153918.372
E - 573649.950

2003 Westwood Professional Services, Inc. found $\frac{3}{4}$ " iron pipe.
County Coordinates by GPS:
NAD 83 (1996 Adjustment)
N- 153918.404
E - 573650.461

2008 The County Surveyor's Office searched and found the $\frac{3}{4}$ " iron pipe as set by Oliver in 1996. Corner fits a lost position, between the E $\frac{1}{4}$ Cor. of Sec. 13 and the E $\frac{1}{4}$ Cor. of Sec. 12. Distances to said E $\frac{1}{4}$ Cor. of Sec. 13 and Sec. 12 measure 2635.28 ft. and 2634.96 ft., respectively. The corner falls 19 ft.± east of centerline of a north-south gravel road (95th Ave NE), and along an east-west centerline (95th At. NE-Benton Co.; 110th St. NW- Mille Lacs Co.).

County Coordinates obtained by GPS
NAD 83 (1996 Adjustment)
N- 153918.295
E - 573650.440