

Statement of Evidence:

I341

North Quarter Corner of Section 34, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

16" Bur Oak	S 85 E	43 links
30" Bur Oak	N 81 W	64 links

A line tree was noted as a 10" Elm West 0.50 chains.

1902 County Surveyor's Record Book A, Map No. 38, shows a survey of Section 27 by John Whilt. Corner is shown as a post with distances of 40.23 chains (2655.18 feet) to the SW corner and 39.51 chains (2607.66 feet) to the SE corner.

1926 County Engineer's notebook No. 49 contains survey for CR 4 running west to east. Notes show 1/4 corner 1.2 feet right of POT on fence lines north and south with same ties as listed in County Surveyor's Record Book 2, pages 438 & 452:

TP	NE	31.5
CorFP	S	34.4

Later ties for POT: 18" Box elder SE 72.2
PP SW 43.2

Stationing gives distances of 2634.6 feet to the NW corner and 2599.4 feet to the NE corner.

1940's County Engineer's Notebook No. 160 contains road survey for SAR No. 4 running west to east along the section line. Corner is shown 1.2 feet right of POT with fence lines north and south. Ties to POT:

18" Box Elder	SE	72.2'
PP	SW	43.2'
10" Elm	S	73.0'

Stationing gives distances of 2636.5 feet to the NW corner and 2598.5 feet to the NE corner to the POT.

1993 Sidney Williamson, LS 10918, found a 1/2 " solid iron pin and replaced with a CIM. Filed Certificate of Location (No. 227422). Distances given: 2633.62 feet to the NW corner and 2601.10 feet to the NE corner of Section 34.

Note: Corner found in 1993 appears to be within 8 feet of the proportion to the 1902 survey, which probably is within reasonable tolerance with the overall section line distances being 28 feet different. Corner is about 3 feet west of the highway information.

2003 County Coordinates computed from traverse information furnished by Surveying & Engineering Professionals, Inc.
County Coordinates NAD 83 (1996 Adjustment) obtained by GPS
N- 137828.884
E- 560723.384

2008 The County Surveyor's Office searched and found a 1/2" iron pipe approximately 0.2' below the surface of the centerline of an east-west bituminous road (County Road No. 4) and on line with a south fence line. Distances measured to the NW and NE corners are 2633.58 feet and 2600.92 feet respectively. These distances check well with the above 1926 distances and subsequent surveys. Surveyor accepts the position as marking the corner and ties were made.
County Coordinates NAD 83 (1996 Adjustment) obtained by GPS
N- 137828.911
E- 560723.444