

Statement of Evidence:

North Quarter Corner of Section 13, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

10" W Birch	N 40 E	7 links
12" W Birch	S 15 W	37 links

A line tree is noted as a 12" W Birch West 0.29 chains.

2002 No resurvey information was found on this corner in the Benton County records.

2003 Survey & Engineering Professionals, Inc. (Linda Brown, LS 23682) found a spike in east-west road and in line with fence to the south. Spike was found to be on line between section corners and 35.34 feet west of the lost position, with a distance of 5194.99 feet between section corners. Spike was accepted as marking the obliterated corner position. On 4/8/03 a ½ " iron pipe with cap was set at the found spike and ties taken.

County Coordinates by Traverse (SEPI)
NAD 83 (1996 Adjustment)
N- 153877.609
E- 571017.436

2003 Westwood Professional Services, Inc. found iron pipe with cap No. 23682.

County Coordinates by GPS
NAD 83 (1996 Adjustment)
N- 153877.902
E – 571017.746