

Statement of Evidence:

I343

East Quarter Corner of Section 34, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded.

18" Bur Oak	S 28 E	52 links
9" Blk Ash	S 13 W	44 links

1901 County Surveyor's Record Book A, Map No. 35, contains a survey of Section 35 by John Whilt with a distance of 39.04 chains (2576.64 feet) to the NW corner and a distance of 38.73 chains (2556.18 feet) to the SW corner of Section 35. Type of corner monument is not given.

2001 Westwood Professional Services, Inc. found a RR spike in the center of north-south road and in line with fence west.

Note: RR spike needs to be located and compared to 1901 survey before using.

2003 County Coordinates computed from traverse information furnished by Surveying & Engineering Professionals, Inc.

NAD 83 (1996 Adjustment)

N- 135288.300

E- 563361.705

Note: Measures 2577.69 feet to the NE corner and 2557.24 feet to the SE corner.

2011 The County Surveyor's Office found a ½ inch iron pipe with cap No. 23682 in the center of the North-South road with a distance of 2577.69 feet to the Northeast corner and 2557.24 feet to the Southeast corner, fitting the 1901 information proportional within about a foot. The ½ inch iron pipe with cap No. 23682 is accepted as the restored position by lost latitudinal location and obliterated longitudinal location of the 1901 resurvey.