

Statement of Evidence:

I323

East Quarter Corner of Section 32, Township 37 North, Range 28 West, Maywood Township, 4th Principal Meridian, Benton County, Minnesota.

1855 Original US General Land Office survey set a wood post at this location and bearing trees were recorded:

10" Blk Ash	S 63 E	43 links
5" Bur Oak	N 81 W	28 links

1938 County Engineers' Notebook No. 119 shows survey of CAR 27 running from north to south. Notes show assumed corner being a hub set in center of road on east and west fence lines. Ties:

FP	W	35.1'
FP	NE	47.3'

Stationing gives distances of 2487 feet to the NE corner and 2595.8 feet to the SE corner with a delta angle of 0-34' left.

2004 Certificate of Survey by David Regan, LS 12236, shows RR spike at corner 2486.46 feet south of the NE corner.

2012 The Benton County Surveyor's Office set a 1/2 inch iron pipe with cap No. 19552 in the center of the North-South road with a distance of 2486.58 feet to the Northeast corner and 2595.36 feet to the Southeast corner. The 1/2 inch iron pipe with cap No. 19552 is accepted as the restored position of the 1938 corner referenced in the County Engineers' Notebook No. 119. Corner was restored by lost latitudinal location and obliterated longitudinal location.

County Coordinates
NAD 83 (1996 Adjustment)
N- 135199.554
E- 552770.928